



Peugeot 2008: J910RR

Vinnumber:	VR3UKZXZLJ814766	Versionname:	e-2008 100kW/ 50kWh Allure
First Registrationdate:	15/10/2020	Fiscalpower:	
Expertise Mileage:	89083	Power Kw:	100
Bodytype:		Body colour	Black
Gearbox:	Automatic	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	112
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 96 / H / Aluminium	5,9 mm	Bridgestone	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	5,1 mm	Bridgestone	Summer
Rear	Left	215 / 60 / 17 / 96 / H / Aluminium	4,5 mm	Michelin	Summer
	Right	215 / 60 / 17 / 96 / H / Aluminium	3,8 mm	Michelin	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)





Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Bumper moulding R, Scratch(es), Replace and paint



Bumper corner RR, Scratch(es), Repair and paint (complete)




Bumper corner RL, Scratch(es), Repair and paint (complete)





Roof, Dent(s) and scratch(es), Repair and paint (complete)



Wheel arch cover FR, Scratch(es), Replace

