


Vehicle details

VIN	VR3UPMHD N5887206	Brand	PEUGEOT	Maintenance date	-
Licence Plate	R0-64-XG	Model	208 Active 1.2 PureTech 75 5d PCV	Maintenance mileage	-
Registration date	14/12/2022	Year	2022	Exterior Color	Grey Metallic
Odometer	62 688 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	25/06/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Bridgestone 185/65/15 Summer 3.5 mm
 Bridgestone 185/65/15 Summer 3.5 mm
 Bridgestone 185/65/15 Summer 5.5 mm
 Bridgestone 185/65/15 Summer 5.0 mm

Exterior

1		Part	Door	4		Part	Step plate
		Position	Front left			Position	Back left
		Damages	Dent & Chips			Damages	Dented
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	For info

Interior damage

<p>2</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Rear parcel shelf brackets</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </tbody> </table>	Part	Rear parcel shelf brackets	Position	Back	Damages	Missing	Severity	-	Repair mode	Replace	<p>3</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Seat</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </tbody> </table>	Part	Seat	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Rear parcel shelf brackets																						
Position	Back																						
Damages	Missing																						
Severity	-																						
Repair mode	Replace																						
Part	Seat																						
Position	Front																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						
<p>5</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Seat</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </tbody> </table>	Part	Seat	Position	Back	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning												
Part	Seat																						
Position	Back																						
Damages	Stained/dirty																						
Severity	-																						
Repair mode	Cleaning																						