

Vehicle details

VIN	VR3UPMHMD NT066123	Brand	PEUGEOT	Maintenance date	-
Licence Plate	R7-96-DB	Model	208 Allure 1.2 PureTech 75 5d	Maintenance mileage	-
Registration date	28/07/2022	Year	2022	Exterior Color	White Solid
Odometer	68 508 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		


Inspection Details

Inspection date	21/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment	Removable element	Technical Document
Automated air-conditioning <input checked="" type="checkbox"/>	Spare wheel kit <input checked="" type="checkbox"/>	User manual <input checked="" type="checkbox"/>
Cruise control <input checked="" type="checkbox"/>	Rear parcel shelf <input checked="" type="checkbox"/>	Warranty booklet <input checked="" type="checkbox"/>
Alloy wheel rims <input checked="" type="checkbox"/>		Remote key <input checked="" type="checkbox"/>
Central locking <input checked="" type="checkbox"/>		Spare key <input checked="" type="checkbox"/>
Electric windows <input checked="" type="checkbox"/>		
Park Distance Control <input checked="" type="checkbox"/>		
Audio System <input checked="" type="checkbox"/>		
Led lighting <input checked="" type="checkbox"/>		

Tyres

Pirelli 195/55/16 Summer 6.0 mm 		Pirelli 195/55/16 Summer 6.0 mm 
Pirelli 195/55/16 Summer 5.0 mm 		Pirelli 195/55/16 Summer 4.0 mm

Exterior

2		<table border="0"> <tr><td>Part</td><td>Roof wind deflector</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof wind deflector	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	3		<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Hail damaged</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Roof	Position	-	Damages	Hail damaged	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Roof wind deflector																								
Position	-																								
Damages	Chemical deposit																								
Severity	-																								
Repair mode	Lumpsum repair																								
Part	Roof																								
Position	-																								
Damages	Hail damaged																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
4		<table border="0"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Hail damaged</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Hail damaged	Severity	Diameter (mm) > 20	Repair mode	Smart Repair													
Part	Bonnet																								
Position	-																								
Damages	Hail damaged																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								

Interior damage

1		<table border="0"> <tr><td>Part</td><td>Spare key</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Spare key	Position	-	Damages	Missing	Severity	-	Repair mode	Replace
Part	Spare key											
Position	-											
Damages	Missing											
Severity	-											
Repair mode	Replace											