



# PEUGEOT 208

## 208 100 S&S BVM6 Allure

VIN NO VR3UPHNE2S4059853  
Registration Number HC975NF



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	9827 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2025-03-21	-

### Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250912144242
Inspection Date / Place	2025-09-12 / BCA AUNAY	Cosmetic Grade	3

### Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1199
Engine Size	1.2	No of Doors	5
Body Type	Flatbed Truck	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	116

### Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warrenty			







Equipment


Central locking	Radio	Alloys wheels	Front parking sensors
Electrically folding wing mirrors	Rear parking sensors	Cruise control	Power assisted steering

Equipment Details

Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

8 Dommages




0 Dommages



Component	Damage	Comments
1 Door / Front Right	Paint / Scratch / Line	
2 Side Panel / Back Right	Paint / Scratch / Line	
3 Door / Back Right	Paint / Scratch / Line	
4 Fender / Front Right	Paint / Scratch / Line	
5 Bumper / Front	Bodywork / Breakage / Crack	
6 Door / Front Left	Paint / Scratch / Line	
7 Tailgate	Paint / Scratch / Line	
8 Bumper / Back	Paint / Scratch / Line	





1. Door / Front Right  
Paint / Scratch / Line -



2. Side Panel / Back Right  
Paint / Scratch / Line -




3. Door / Back Right  
Paint / Scratch / Line -



4. Fender / Front Right  
Paint / Scratch / Line -



5. Bumper / Front  
Bodywork / Breakage / Crack -



6. Door / Front Left  
Paint / Scratch / Line -





7. Tailgate  
Paint / Scratch / Line -



8. Bumper / Back  
Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*