


Vehicle details

VIN	VR3UPHNEK LT114924	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J2-36-VF	Model	208 Blue Lease Allure 1.2 PureTech 100	Maintenance mileage	-
Registration date	28/10/2020	Year	2020	Exterior Color	Black Metallic
Odometer	84 240 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	30/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Panoramic roof	✓
Alloy wheel rims	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Continental 195/55/16 Winter 6.5 mm		Continental 195/55/16 Winter 6.5 mm	
Vredestein 195/55/16 Winter 6.0 mm		Vredestein 195/55/16 Winter 6.0 mm	

Exterior

<p>1</p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Roof post A/B/C</td></tr> <tr><td>Position</td><td>Left</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof post A/B/C	Position	Left	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>3</p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scatched	Severity	-	Repair mode	Repair
Part	Roof post A/B/C																						
Position	Left																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Bumper																						
Position	Front																						
Damages	Scatched																						
Severity	-																						
Repair mode	Repair																						
<p>4</p>  <p>● ● ● ● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>5</p>  <p>● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Alloy wheel 16"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 16"	Position	Front right	Damages	Scatched	Severity	-	Repair mode	Lumpsum repair
Part	Bonnet																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Alloy wheel 16"																						
Position	Front right																						
Damages	Scatched																						
Severity	-																						
Repair mode	Lumpsum repair																						

Interior damage

<p>2</p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Rear parcel shelf retaining strap hook</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Rear parcel shelf retaining strap hook	Position	Back	Damages	Missing	Severity	-	Repair mode	Replace
Part	Rear parcel shelf retaining strap hook										
Position	Back										
Damages	Missing										
Severity	-										
Repair mode	Replace										