



PEUGEOT 208: 1YJJ010			
Vinnumber:	VR3UPHNKSLT088062	Versionname:	1.2 PureTech 100 EAT8 S&S €6.3 GT Line
First Registrationdate:	10/09/2020	Fiscalpower:	
Expertise Mileage:	80717	Power Kw:	74
Bodytype:		Body colour	White
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1332
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	2	Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

Summer tyres:	205/45/17/88 H			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/45 R 17 88 H
Tyre size FR				205/45 R 17 88 H
Tyre size RL				205/45 R 17 88 H
Tyre size RR				205/45 R 17 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	885,18
Bonnet, Stone chip(s), Acceptable	0,00



Alloy rim FL polished, Scratch(es), Acceptable	0,00
--	------



Door FL, Dent(s), Acceptable	0,00
------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)	329,39
---	--------



Boot moulding, Scratch(es), Repair and paint (complete)	157,71
---	--------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Door FR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Door RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------



Bodywork, Not original part, Remove lettering	0,00
---	------

