



# PEUGEOT 208

## 208 PureTech 100 S&S EAT8 GT

VIN NO VR3UPHNKSMTO88315  
Registration Number GN512TS



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2022-11-23

Odometer Reading



38466 km

Country First Registered



France

### Inspection Report Summary

|                         |                        |                |                 |
|-------------------------|------------------------|----------------|-----------------|
| Customer                | BCAuto Encheres        | Report Number  | P20250728091447 |
| Inspection Date / Place | 2025-07-28 / BCA AUNAY | Cosmetic Grade | 2               |

### Vehicle Summary

|                    |             |                    |                         |
|--------------------|-------------|--------------------|-------------------------|
| Vehicle Condition  | Not Movable | VAT Type           | Qualified - Normal Rate |
| Fuel Type          | Petrol      | Gearbox Type       | Automatic               |
| Colour             | Red         | Engine Size (cc)   | 1199                    |
| Engine Size        | 1.2         | No of Doors        | 5                       |
| Body Type          | Hatchback   | Drive Train        | Front                   |
| Seat Colour        |             | No of Seats        | 5                       |
| Seat Covering Name |             | Seat Covering      | Cloth                   |
| Charging Cables    |             | WLTP CO2 Emissions |                         |

### Vehicle History & Documents

|                        |            |                      |    |
|------------------------|------------|----------------------|----|
| Service Book Available | -          | Next Service Mileage | km |
| Previous Usage         | Normal Use | Imported             |    |
| Manufacturer Warrenty  |            |                      |    |





Equipment

|                                   |                      |                   |                         |
|-----------------------------------|----------------------|-------------------|-------------------------|
| Central locking                   | Radio                | Alloys wheels     | Power assisted steering |
| Electrically folding wing mirrors | Rear parking sensors | Stability control | Satellite navigation    |


Equipment Details

|              |    |                  |    |
|--------------|----|------------------|----|
| Seat Heating | No | Air Conditioning | No |
|--------------|----|------------------|----|




## Cosmetic Damage

2 Dommages



0 Dommages



| Component |                  | Damage                        | Comments |
|-----------|------------------|-------------------------------|----------|
| 1         | Hood             | Bodywork / Dent / Deformation |          |
| 2         | Rim / Front Left | Out of Bodywork / Breakage    |          |



1. Hood  
Bodywork / Dent / Deformation -



2. Rim / Front Left  
Out of Bodywork / Breakage -

Mechanical Condition


Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*