



## Peugeot 208: J438ND

|                         |                   |                        |                                    |
|-------------------------|-------------------|------------------------|------------------------------------|
| Vinnumber:              | VR3UPHNSSLT072032 | Versionname:           | 208 1.2 Puretech 96kW GT-Line EAT8 |
| First Registrationdate: | 23/10/2020        | Fiscalpower:           |                                    |
| Expertise Mileage:      | 99349             | Power Kw:              | 96                                 |
| Bodytype:               |                   | Body colour            | Blue Vertigo metaallak             |
| Gearbox:                | Automatic         | Paint type             | Metalic                            |
| Transmission:           | Front             | Type of rims (mounted) | Aluminium                          |
| Fueltype:               | Petrol            | Parking lot            | 453                                |
| Number of seats         | 5                 |                        |                                    |
| Type of rims (mounted)  | Aluminium         |                        |                                    |
| Maintenance needed      | Yes               |                        |                                    |

## Options

|                       |   |                            |
|-----------------------|---|----------------------------|
| Number of keys total  | 2 | Telephone equipment        |
| GPS                   |   | Panoramic roof             |
| Autom climate control |   | Central consol F           |
| Windows electric F    |   | Luggage cover              |
| Radio multimedia      |   | Headlights Xenon/LED/Laser |
|                       |   | Front parking sensors      |
|                       |   | Rear parking sensors       |

## Tyres

| Location | Position | Measures                           | Depth  | Make     | Type   |
|----------|----------|------------------------------------|--------|----------|--------|
| Front    | Left     | 205 / 45 / 17 / 88 / V / Aluminium | 5,1 mm | Michelin | Summer |
|          | Right    | 205 / 45 / 17 / 88 / V / Aluminium | 4,9 mm | Michelin | Summer |
| Rear     | Left     | 205 / 45 / 17 / 88 / V / Aluminium | 5,0 mm | Michelin | Summer |
|          | Right    | 205 / 45 / 17 / 88 / V / Aluminium | 5,3 mm | Michelin | Summer |

## Assistance equipment

|                                          |   |
|------------------------------------------|---|
| Number of charging cables (normal)       | 0 |
| Number of charging cables (rapid charge) | 0 |

## Service, Maintenance, Execute



## Door RL, Scratch(es), Repair and paint (complete)



## Door FL, Scratch(es), Repair and paint (complete)



## Bonnet, Stone chip(s), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)

