



PEUGEOT 2008: 1YFF952

Vinnumber:	VR3USHNSKLJ769179	Versionname:	1.2 Puretech 96kW S&S Allure
First Registrationdate:	12/08/2020	Fiscalpower:	
Expertise Mileage:	89166	Power Kw:	96
Bodytype:		Body colour	Orange
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3127
Fueltype:	Petrol		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

215/60/17/96 H				
Winter tyres:	Fr.L.	Vredestein: 4 mm	Fr.R.	Vredestein: 4 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Continental: 4 mm
Tyre profile depth FL	4.0			
Tyre profile depth FR	4.0			
Tyre profile depth RL	4.0			
Tyre profile depth RR	4.0			
Tyre size FL	215/60 R 17 96 H			
Tyre size FR	215/60 R 17 96 H			
Tyre size RL	215/60 R 17 96 H			
Tyre size RR	215/60 R 17 96 H			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	2480			
Tyre make FR	2480			
Tyre make RL	2480			
Tyre make RR	256			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1795,69
Seat cover FR, Stain, Cleaning	28,43



Bumper F, Deformed / Strained, Replace and paint	931,41
--	--------



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)	300,51
---	--------




Wing trim FL, Scratch(es), Replace	123,60
------------------------------------	--------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim RL polished, Chemical polution, Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------




Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)	411,74
---	--------





Alloy rim RR polished, Chemical polution, Acceptable	0,00
--	------



Outside rear-view mirror housing R, Scratch(es), Acceptable	0,00
---	------

