


Vehicle details

VIN	VR3USHNSK MJ557302	Brand	PEUGEOT	Maintenance date	-
Licence Plate	K2-61-RL	Model	2008 Blue Lease Allure 1.2 PureTech 130 5d	Maintenance mileage	-
Registration date	17/02/2021	Year	2021	Exterior Color	Black Metallic
Odometer	85 280 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	07/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Pirelli 215/60/17 Winter 7.5 mm



Pirelli 215/60/17 Winter 7.5 mm



Pirelli 215/60/17 Winter 8.0 mm

Pirelli 215/60/17 Winter 8.0 mm

Exterior

1



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

3



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

5



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

7



Part	Alloy wheel 17"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8



Part	Wing
Position	Back left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair