



PEUGEOT 2008: 2DSF527

Vinnnumber:	VR3USHNSKPJ667536	Versionname:	2008 1.2 Puretech S/S Active Pack 96kW/130pk
First Registrationdate:	9/06/2023	Fiscalpower:	5D/P Man-6 - CO2 incomplet
Expertise Mileage:	45058	Power Kw:	
Bodytype:		Body colour	White
Gearbox:	MAN 6 VIT	Parking lot	d34t
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol		
Number of seats	5		
Bodywork	Clean		
Registration Certificate Car (BE)	Yes		
Number of doors	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Interior	Clean		

Options

Rims alloy		Front parking sensors
Number of keys total	1	Radio
Windows electric F		Rear parking sensors
Airco electronic		
Steering wheel multifunctional		
Navigation with screen		
Number keys remote	1	
Windows electric R		
Cruise Control		

Limited Technical Inspection

Engine startingtime	OK	Sound engine	OK
Idle position	OK	Transmission	OK
Exhaust gass	OK	Clutch test	OK

Tyres

216/65/16/98 H				
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm
Tyre size RR	216/65 R 16 98 H			
Tyre make RR	256			
Tyre profile depth FL	3.0			
Tyre type FR	Summer			
Tyre size FL	216/65 R 16 98 H			
Tyre make FL	256			
Tyre profile depth RL	3.0			
Tyre type RR	Summer			
Tyre make RL	256			
Tyre size RL	216/65 R 16 98 H			
Tyre type FL	Summer			
Tyre profile depth FR	3.0			
Tyre type RL	Summer			
Tyre make FR	256			
Tyre size FR	216/65 R 16 98 H			
Tyre profile depth RR	3.0			

Assistance equipment

Number of charging cables (rapid charge)	0	Compressor	Yes
Repair kit	Yes		
Number of charging cables (normal)	0		


Ignition key, Missing, Replace




Bumper spoiler F, Scratch(es), Replace



Bumper F, Scratch(es), Acceptable







Wing trim FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable




Bumper moulding R, Scratch(es), Acceptable



Boot cover, Broken, Replace



Door FR, Scratch(es), Acceptable



Wing trim FR, Scratch(es), Replace



Roof, Scratch(es), Polish

