


Vehicle details

VIN	VR3USHNSS LJ657881	Brand	PEUGEOT	Maintenance date	-
Licence Plate	H1-28-RX	Model	2008 Blue Lease Allure 1.2 PureTech 130 EAT8 5d	Maintenance mileage	-
Registration date	24/04/2020	Year	2020	Exterior Color	Black Metallic
Odometer	221 247 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	04/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/60/17 Summer 3.0 mm		Bridgestone 215/60/17 Summer 2.0 mm	
Michelin 215/60/17 Summer 5.0 mm		Bridgestone 215/60/17 Summer 2.0 mm	

Exterior

3		Part Alloy wheel 17" Position Front left Damages Scratched Severity - Repair mode Lumpsum repair	5		Part Door Position Back left Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair
6		Part Alloy wheel 17" Position Back left Damages Scratched Severity - Repair mode Lumpsum repair	7		Part Bumper Position Back Damages Scratched Severity Length (cm) > 10 Repair mode Repair
8		Part Bumper moulding Position Back Damages Scratched Severity Length (cm) > 10 Repair mode Repair	11		Part Alloy wheel 17" Position Back right Damages Scratched Severity - Repair mode Lumpsum repair
12		Part Alloy wheel 17" Position Front right Damages Scratched Severity - Repair mode Lumpsum repair	13		Part Bumper moulding Position Front Damages Scratched Severity Length (cm) > 10 Repair mode Repair

Interior damage

1		Part Interior cleaning Position Front right Damages Stained/dirty Severity - Repair mode Cleaning	2		Part Boot carpet Position Back Damages Scratched Severity - Repair mode Smart Repair
4		Part Seat upholstery mixed Position Front left Damages Cut Severity - Repair mode For info	14		Part Interior tailgate lining Position Back Damages Scratched Severity - Repair mode Replace

Others

9		Part Wiper arm Position Back Damages Broken Severity - Repair mode Replace	10		Part Wiper blade Position Back Damages Missing Severity - Repair mode Replace
---	---	--	----	--	---