

Vehicle details

VIN	VR3USHNSS LJ752125	Brand	PEUGEOT	Maintenance date	-
Licence Plate	J5-96-HN	Model	2008 Blue Lease Allure 1.2 PureTech 130 EAT8 5d	Maintenance mileage	-
Registration date	28/08/2020	Year	2020	Exterior Color	Black Solid
Odometer	162 103 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	02/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/55/18 Summer 5.5 mm



Michelin 215/55/18 Summer 5.5 mm



Michelin 215/55/18 Summer 5.0 mm

Michelin 215/55/18 Summer 5.0 mm

Exterior

1		Part: Step plate Position: Front left Damages: Dent & Chips Severity: - Repair mode: For info	2		Part: Step plate Position: Back left Damages: Scratched Severity: - Repair mode: For info
7		Part: Bumper moulding Position: Back Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	8		Part: Wing Position: Back right Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Repair
9		Part: Door Position: Back right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	10		Part: Step plate Position: Front right Damages: Dent & Chips Severity: - Repair mode: For info
11		Part: Bonnet trim Position: Front right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	12		Part: Bumper Position: Front Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair
13		Part: Bonnet Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	14		Part: Roof Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair

Interior damage

3		Part: Fabric seat Position: Front left Damages: Not conform Severity: - Repair mode: For info	4		Part: Interior tailgate lining Position: Up Damages: Scratched Severity: - Repair mode: Smart Repair
5		Part: Interior tailgate lining Position: Back left Damages: Scratched Severity: - Repair mode: Smart Repair	6		Part: Interior tailgate lining Position: Back right Damages: Scratched Severity: - Repair mode: Smart Repair