


Vehicle details

VIN	VR3USHNSS NJ545365	Brand	PEUGEOT	Maintenance date	-
Licence Plate	P9-66-JZ	Model	2008 Allure Pack 1.2 Puretech 130 EAT8 5d Onze Dea	Maintenance mileage	-
Registration date	31/03/2022	Year	2022	Exterior Color	Grey Metallic
Odometer	85 661 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	23/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 215/60/17 Summer 4.0 mm		Continental 215/60/17 Summer 4.0 mm	
Continental 215/60/17 Summer 6.0 mm		Continental 215/60/17 Summer 6.0 mm	

Exterior

2



Part	Wing
Position	Back left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

3



Part	Roof wind deflector
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Wing
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5



Part	Door
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Exterior door mirror shell
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning