



CITROEN C5 AIRCROSS: GA-928-EB

Vinnumber:	VR7A4DGZ5ML034803	Versionname:	
First Registrationdate:	22/06/2021	Fiscalpower:	
Expertise Mileage:	126512	Power Kw:	
Bodytype:	SUV	Body colour:	Dark Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Luggage cover
Number keys remote	2	Rear view camera
GPS big screen color		
GPS storage		
GPS storage	HD	

Degree of wear

225/55/18/102 V				
Summer tyres:	Fr.L.	Michelin: 40%	Fr.R.	Michelin: 40%
	Re.L.	Michelin: 30%	Re.R.	Michelin: 35%
Tyre profile depth FL				5.5
Tyre profile depth FR				5.5
Tyre profile depth RL				6.1
Tyre profile depth RR				5.8
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Malfunction indicator, Blinking, Check



Tyres, No damage, Acceptable



Alloy rim FR, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Wing trim FL, Unclassped, Dismount/Mount



Door FL, Dent(s), Repair and paint (complete)



Bumper F, Deformed / Strained, Replace and paint



Door FR, Dent(s), Repair and paint (complete)



Boot lid covering B, Scratch(es), Repair/replace (lump sum)



Roof, Hail damage, Paintless dent repair (hail)

