



CITROEN C5 Aircross: 2ADF087

Vinnnumber:	VR7ACYHZSLL100110	Versionname:	C5 Aircross 1.5 BlueHDi 130 S/S EAT8 Bus. GPS
First Registrationdate:	25/02/2021	Fiscalpower:	105g 96kW/131pk 5D/P Auto-8
Expertise Mileage:	111178	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:	Front	Parking lot	A109
Fueltype:	Diesel		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Bodywork	Clean		
Interior	Dirty		

Options

Number of keys total	2	Radio
Number keys remote	2	Front parking sensors
GPS storage		Rear parking sensors
GPS storage	HD	Fog lights (front)
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Navigation with screen		
Airco electronic		
Rims alloy		

Limited Technical Inspection

Airco functioning	Yes	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Transmission	OK
Exhaust gass	OK		

Degree of wear

225/55/18/102 V				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				6.0
Tyre profile depth RL				4.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bonnet, Dent(s), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable



Roof, Hail damage, Paintless dent repair (hail)

