



ARVAL
BNP PARIBAS GROUP

2BUN049

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	282326
License plate	2BUN049
Vehicle identification number	VR7ACYHZSNL007838
Dossier	2021267009
Make	Citroen C5 Aircr.1.5BHDi 130 B
Mileage	95326.00
First registration	28/03/2022
	23/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
866	Lettering Removal // XL Special	N
14	Bumper Front // Repair & Painting	N
33	Front Bonnet // Repair & Painting	N
40	Windshield // Repair	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
159	Rear Bonnet / Rear Window / Replace	N
174	Light / Rear Right / Replace	Y
191	Door Rear Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
881	Key Price Range 1 //	N


Damage Pictures




Wheel Alloy Front Right // Repair-scratch




Light / Rear Right / Replace-scratch




Rear Bonnet / Rear Window / Replace-scratch






Light / Rear left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Front Bonnet // Repair & Painting-dent




Door Front Right // Repair & Painting-dent




Door Rear Right // Smart Repair Medium-dent



Wing Rear Left // Repair & Painting-scratch + dent




Bumper Front // Repair & Painting-bad repair



Windshield // Repair-glass damage



Key Price Range 1 //-missing





Lettering Removal // XL Special-