


Vehicle details

VIN	VR7ARHNSJ LL033138	Brand	Citroën	Maintenance date	-
Licence Plate	H0-07-SN	Model	C5 Aircross PureTech 130 S;S Business Plus 5d	Maintenance mileage	-
Registration date	04/05/2020	Year	2020	Exterior Color	Green Metallic
Odometer	91 757 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	21/07/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Leather	✓
GPS system	✓
Alloy wheel rims	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Pirelli 205/55/19 Winter 5.0 mm



Pirelli 205/55/19 Winter 5.0 mm



Pirelli 205/55/19 Winter 4.0 mm

Pirelli 205/55/19 Winter 5.0 mm

Exterior

2



Part

Position

Damages

Severity

Repair mode

Door

Front left

Dent & Chips

Diameter (mm) > 20

Repair

3



Part

Position

Damages

Severity

Repair mode

Door

Back left

Chemical deposit

-

Lumpsum repair

5



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Dent & Chips

Diameter (mm) > 20

Repair

7



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Scratched

Length (cm) > 10

Repair

8



Part

Position

Damages

Severity

Repair mode

Roof post A/B/C

Right

Dented

Diameter (mm) > 20

Smart Repair

9



Part

Position

Damages

Severity

Repair mode

Alloy wheel 19"

Front right

Scratched

-

Lumpsum repair

10



Part

Position

Damages

Severity

Repair mode

Wing moulding

Front right

Scratched

Length (cm) > 10

Repair

11



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Scratched

Length (cm) > 10

Repair

12



Part

Position

Damages

Severity

Repair mode

Roof

-

Dented

Diameter (mm) > 20

Repair

13



Part

Position

Damages

Severity

Repair mode

Unpainted bumper

Back

Scratched

Length (cm) > 10

Repair

Interior damage

1



Part

Interior cleaning

Position

Front left

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

●

●

●

4



Part

Interior cleaning

Position

Back

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

●

●

6



Part

Interior tailgate lining

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Replace

●