



Citroën Berlingo (Segm. B1): 1XTQ124

Vinnumber:	VR7EFYHYCLJ590846	Versionname:	Berlingo M Light Control 1.5 BlueHDi S&S 100pk/cv
First Registrationdate:	18/05/2020	Fiscalpower:	
Expertise Mileage:	36334	Power Kw:	73
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	35980 km		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Type of Tow bar	Tow bar fixed
Type of Maintenance book	Maintenancebook present		
Type of GPS storage	N.A.		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Data erasure, Maintenance, Check

No pictures to display

Interior, Dirty, Forfeit



Seat cover FL, Hole, Replace



Floor covering FL, Damaged, Smart repair



Bumper F, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Replace



Steel rim FL, Rust, Acceptable



Outside rear-view mirror housing L, Scratch(es), Replace



Outer sill L, Dent(s) and scratch(es), Acceptable



Door trim FL, Scratch(es), Replace



Door RL, Dent(s) and scratch(es), Repair and paint (complete)




Door trim RL, Scratch(es), Replace



Wing RL, Dent(s), Paintless dent repair



Steel rim RL, Rust, Acceptable



Rear bulkhead lining, Damaged, Check





Rubber seal for boot lid, Deformed / Strained, Acceptable



Bumper R, Broken, Replace



Rear light R, Broken, Replace



Boot door panel RR, Deformed / Strained, Replace and paint



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Steel rim FR, Rust, Acceptable



Steel rim RR, Rust, Acceptable



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Deformed / Strained, Replace and paint



Door FR, Deformed / Strained, Replace and paint



Door trim FR, Scratch(es), Replace



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable

