




GENERAL INFO

File	280757
License plate	26454
VIN	VR7ERHNP2KJ757027
Dossier	2019 125 457 / 241626
Make / Model	Citroen Ber.Mult.1.2PT 110 Live M
Mileage	109485
1st inscription	28/10/2019
Start from	
Available from	12/07/2024



CHECK POINTS

Description	Number	Pres	Remark
Original license plate		Y	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)			
Certificate of conformity			
Registration certificate Part 1			
Repair kit			
RunOnFlat			
Charging cable			

DAMAGES

Id	Damage	Dossier nbr	Acceptable damage
OTHER DAMAGE(S)			
106	Door Rear Left // Polish		Y
174	Light / Rear Right / Replace		Y
186	Wing Rear Right // Polish		Y
211	Door Front Right // Smart Repair Medium		Y
DAMAGE 224.225.050			
80	Door Front Left // Smart Repair Small	224.225.050	N
344	Wheel Front Right / Wheel Cover / Replace	224.225.050	N
860	Interior Cleaning // Small	224.225.050	N
881	Key Price Range 1 //	224.225.050	N

If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site (Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem) .

DAMAGE PICTURES

Damage within Renta-norm


OTHER DAMAGES



Door Front Left // Smart Repair Small: AA - Scratch +Dent



Door Rear Left // Polish: E - Scratch




Light / Rear Right / Replace: E - Scratch



Wing Rear Right // Polish: E - Scratch



Door Front Right // Smart Repair Medium: E - Scratch



Wheel Front Right / Wheel Cover / Replace: R - Missing



Interior Cleaning // Small: U - Filthy



Key Price Range 1 //: R - Missing