

GENERAL INFO

File	280757
License plate	26172
VIN	VR7ERHNPJKJ700749
Dossier	2019 125 073 / 228561
Make / Model	Citroen Ber.Mult.1.2PT 110 Live M
Mileage	94392
1st inscription	22/07/2019
Start from	
Available from	23/01/2024

CHECK POINTS

Description	Number	Pres	Remark
Original license plate		Y	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)			
Certificate of conformity			
Registration certificate Part 1			
Repair kit			
RunOnFlat			
Charging cable			



DAMAGES

Id	Damage	Dossier nbr	Acceptable damage
OTHER DAMAGE(S)			
40	Windshield // Repair		Y
54	Headlight / Front left / Replace		Y
165	Roof // Polish		Y
860	Interior Cleaning // Small		Y
DAMAGE 224.137.043			
137	Bumper Rear // Replace without painting	224.137.043	N
174	Light / Rear Right / Replace	224.137.043	N
881	Key Price Range 1 //	224.137.043	N

If any missing items (keys, accessories, car documents, etc.) are invoiced you still can return them to Arval within five business days after reception of the inspection report. You may send this by registered letter to / return it on site (Arval Belgium NV/SA, Ikaroslaan 99, 1930 Zaventem) .

DAMAGE PICTURES



Damage within Renta-norm

DAMAGE 1



Bumper Rear // Replace without painting: AA - Scratch +Dent



Light / Rear Right / Replace: D - Broken


OTHER DAMAGES





Windshield // Repair: P - Stone-chip windshield



Headlight / Front left / Replace: D - Broken



Roof // Polish: AD - Chemical reaction



Interior Cleaning // Small: W - Stain

Key Price Range 1 //: R - Missing