



# NISSAN NV200 FOURGON

## NV200 FOURGON 1.5 DCI 90 BUSINESS

VIN NO VSKHBAM20U0131691

Registration Number EF419MD



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20251006222817
Inspection Date / Place	2025-10-06 / BCA INGRANDES	Cosmetic Grade	2

### Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	White	Engine Size (cc)	1461
Engine Size	1.5	No of Doors	4
Family	Light Commercial Vehicle	Drive Train	Front
Seat Colour		No of Seats	2
Charging Cables		NEDC CO2 Rating (q/km)	128
Engine Rating CV	5	Metalic Colour	No
Accident Damage	No	Euro Emission	

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Stability control	Power assisted steering	Radio
Cruise control			

Equipment Details

Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		


Wheels & Tyres

Left Rear Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Right Front Tyre Depth	3




Cosmetic Damage


3 Dommages



1 Dommages



Component	Damage	Comments
1 Tailgate	Paint / Poor Previous Repair	
2 Door / Back Right	Paint / Scratch / Scuff	
3 Corner Bumper / Back Left	Bodywork / Assembly	
4 Seat / Front Left	Interior / Ripped	



1. Tailgate  
Paint / Poor Previous Repair -



2. Door / Back Right  
Paint / Scratch / Scuff -



3. Corner Bumper / Back Left  
Bodywork / Assembly -



4. Seat / Front Left  
Interior / Ripped -

## Mechanical Condition

### Tyres

Presence Anti-Theft Lock Nut 

### Equipments Test

Convertible, Sunroof, Wagon,  
Flatbed truck, Tailgate  
electrics test

NA

Dump / Trail / Tail Gate Lift

NA

Main & Spare Keys  
Functioning



Central Locking



Electric Windows



Audio Equipment



Navigation System

NA

AC / Heating System



Parking Sensors / Cameras  
Functioning

NA

### Levels

Oil - Condition



Level - Oil



Coolant Fluid - Condition



Coolant Fluid



Brakes Fluid



### Engine

Cross Member



Serpentine Belt



Control Liquid Leak



### Dashboard Lights

Dashboard Working



Engine Light



Oil Pressure Warning Light



Airbag Warning Light



Brake Warning Light



Level - Fuel / Battery

15

ABS Warning Light



Transmission Warning Light



Diesel Particulate Filter Light



ESP Fault/Traction Control  
Malfunction Light



4WD Light

NA

Service Light



Steering Fluid Level



### Hybrid/EV

Charge Port Condition

NA

Charge lead 1 condition  
/Charge lead 2 condition

NA

Test Drive Inspection

Test Drive			
Vehicle Starts	✓	Engine functioning	✓
Engine / Aux Belt / Pulley Noise	✓	Steering Noise/Gripping	✓
Smoke Quantity	✓	Transmission	✓
Engine Power	✓	Clutch Functioning	✓
Steering	✓	Brakes Functioning	✓
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.