


Vehicle details

VIN	VSSZZZ5FZ LR042653	Brand	SEAT	Maintenance date	-
Licence Plate	G6-06-ZH	Model	Leon Sportourer ST 1.5 TSI FR Business Intense DSG	Maintenance mileage	-
Registration date	10/01/2020	Year	2020	Exterior Color	Red Solid
Odometer	141 988 km	Engine size	1498	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	13/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Sliding roof	✓
Panoramic roof	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 225/45/17 Summer 4.0 mm		Pirelli 225/45/17 Summer 4.0 mm	
Continental 225/45/17 Summer 4.0 mm		Continental 225/45/17 Summer 2.5 mm	

Exterior

1		Part	Bumber protection film	2		Part	Alloy wheel 17"
		Position	Front			Position	Front left
4		Damages	Broken	5		Damages	Scratched
		Severity	-			Severity	-
6		Repair mode	Replace	7		Repair mode	Lumpsum repair
		Part	Alloy wheel 17"			Part	Door
		Position	Back left			Position	Back right
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	Diameter (mm) > 20
		Repair mode	Lumpsum repair			Repair mode	Smart Repair
		Part	Alloy wheel 17"			Part	Bumper
		Position	Front right			Position	Front
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumpsum repair			Repair mode	Repair
		Part	Alloy wheel 17"			Part	Bumper
		Position	Front right			Position	Front
		Damages	Scratched			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumpsum repair			Repair mode	Repair

Interior damage

3		Part	Interior cleaning
		Position	Back
		Damages	Stained/dirty
		Severity	-
		Repair mode	Cleaning
		Part	Interior cleaning
		Position	Back
		Damages	Stained/dirty
		Severity	-
		Repair mode	Cleaning