



# SEAT Ateca

## Ateca 2.0 TDI DSG

VIN NO VSSZZZ5FZM6543039  
Registration Number FZM6543039



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| 2026-03-01   | 1                    | 2                       | 163150 km                |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| 2025-03-07   | 151323               | 2021-03-29              | Germany                  |

### Inspection Report Summary

|                         |                                       |                |                 |
|-------------------------|---------------------------------------|----------------|-----------------|
| Customer                | BCA Online                            | Report Number  | P20250819083735 |
| Inspection Date / Place | 2025-08-19 / ARS Altmann AG Riedstadt | Cosmetic Grade | 1               |


### Vehicle Summary


|                    |           |                    |                         |
|--------------------|-----------|--------------------|-------------------------|
| Vehicle Condition  | Runner    | VAT Type           | Qualifying              |
| Fuel Type          | Diesel    | Road Worthy        | Yes                     |
| Colour             | White     | Engine Size (cc)   | 1968                    |
| Engine Size        | 2.0       | No of Doors        | 5                       |
| Body Type          | SUV       | Drive Train        | Front                   |
| Seat Colour        |           | No of Seats        | 5                       |
| Seat Covering Name | schwarz   | Seat Covering      | Cloth/Synthetic Leather |
| Charging Cables    |           | WLTP CO2 Emissions |                         |
| Gearbox Type       | Automatic |                    |                         |

### Vehicle History & Documents

|                        |         |                      |    |
|------------------------|---------|----------------------|----|
| Service Book Available | Present | Next Service Mileage | km |
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |







Equipment

|                                  |                                   |                        |                          |
|----------------------------------|-----------------------------------|------------------------|--------------------------|
| Trafficsignrecognition           | USB Socket                        | Alloys wheels          | Anti-lock braking        |
| Cabin Pre Heating                | Diesel particulate filter         | Digitaldashboard       | Headlamp wash/wipe       |
| Highbeamassist                   | Remote central locking            | Roof rails             | Split folding rear seats |
| Distancewarningsystem            | Electrictailgate                  | Leather steering wheel | Radio                    |
| Rear parking sensors             | Trip Computer                     | Airbag Status          | Ambientlighting          |
| Bluetooth telephone interface    | Cruise control                    | Digital Radio          | Front fog lamps          |
| Heated wing mirrors              | Remote adjusting wing mirrors     | Reversing Camera       | Satellite navigation     |
| Stability control                | Electrically folding wing mirrors | Laneassist             | LED Headlamps            |
| Rain sensitive windscreen wipers |                                   |                        |                          |

Equipment Details


|                        |                           |                  |       |
|------------------------|---------------------------|------------------|-------|
| Air Conditioning       | Dual Zone Climate Control | Alloy Wheel Size | 18    |
| Extra Wheel / Tyre Set | Winter Tyres - Alloy      | Seat Heating     | Front |

Wheels & Tyres


|                            |   |                            |   |
|----------------------------|---|----------------------------|---|
| Right Front Tyre Depth     | 3 | Left Front Tyre Depth      | 3 |
| Right Rear Tyre Depth      | 3 | Left Rear Tyre Depth       | 3 |
| Extra Wheel - 1 Tyre Depth | 5 | Extra Wheel - 2 Tyre Depth | 5 |
| Extra Wheel - 3 Tyre Depth | 5 | Extra Wheel - 4 Tyre Depth | 5 |

Cosmetic Damage


1 Schäden



0 Schäden



| Component |                  | Damage                    | Comments |
|-----------|------------------|---------------------------|----------|
| 1         | Rim / Front Left | Out of Bodywork / Scratch |          |



1. Rim / Front Left  
Out of Bodywork / Scratch -

## Mechanical Condition

### Control Lights

|                                 |   |                                              |   |
|---------------------------------|---|----------------------------------------------|---|
| Display Defect                  | ✓ | Service Light                                | ✓ |
| ABS Warning Light               | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Diesel Particulate Filter Light | ✓ | Airbag Warning Light                         | ✓ |
| Oil Pressure Warning Light      | ✓ | Brake Warning Light                          | ✓ |
| Power Steering Warning Light    | ✓ | Alternator / Battery                         | ✓ |
| No Dashboard Lights             | ✓ | Tire Pressure Monitoring System              | ✓ |

### Equipments Test

|                     |   |                                       |   |
|---------------------|---|---------------------------------------|---|
| Other Equipments    | ✓ | Main & Spare Keys Functioning         | ✓ |
| Electric Windows    | ✓ | Navigation System                     | ✓ |
| Audio Equipment     | ✓ | Parking Sensors / Cameras Functioning | ✓ |
| AC / Heating System | ✓ |                                       |   |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Starts       | ✓ | Engine Status / EML | ✓ |
| Engine Leak Visible | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)