



SEAT Arosa

Arosa 1.0

VIN NO VSSZZZ6HZ3R005657

Registration Number HZ3R005657



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2003-04-24

Odometer Reading



85148 km

Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250922141047
Inspection Date / Place	2025-09-22 / Dello Lübeck	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	999
Engine Size	1.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Split folding rear seats	Remote central locking	Radio
---------------	--------------------------	------------------------	-------

Equipment Details


Air Conditioning	No
------------------	----

Wheels & Tyres


Left Rear Tyre Depth	6	Right Rear Tyre Depth	6
Left Front Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage

15 Schäden



2 Schäden



Component		Damage	Comments
1	Tailgate	Paint / Poor Previous Repair	
2	Fender / Front Right	Paint / Poor Previous Repair	
3	Fender / Front Left	Bodywork / Dent / Deformation	
4	Door / Front Left	Bodywork / Dent / Deformation	
5	Fender / Back Left	Bodywork / Dent / Deformation	
6	Roof	Bodywork / Dent / Deformation	
7	Fender / Back Right	Bodywork / Dent / Deformation	
8	Door / Front Right	Bodywork / Dent / Deformation	
9	Fender / Front Left	Paint / Corrosion	
10	Windshield / Front	Paint / Chipping	
11	Door / Front Left	Paint / Chipping	
12	Bumper / Back	Paint / Scratch / Scuff	


13	Bumper / Back	Paint / Scratch / Scuff
14	Fender / Back Right	Paint / Scratch / Scuff
15	Headrest / Back Left	Interior / Missing
16	Headrest / Back Right	Interior / Missing
17	Tailgate	Paint / Chipping




1. Tailgate
Paint / Poor Previous Repair -




2. Fender / Front Right
Paint / Poor Previous Repair -




3. Fender / Front Left
Bodywork / Dent / Deformation -




4. Door / Front Left
Bodywork / Dent / Deformation -



5. Fender / Back Left
Bodywork / Dent / Deformation -



6. Roof
Bodywork / Dent / Deformation -



7. Fender / Back Right
Bodywork / Dent / Deformation -



8. Door / Front Right
Bodywork / Dent / Deformation -



9. Fender / Front Left
Paint / Corrosion -



10. Windshield / Front
Paint / Chipping -



11. Door / Front Left
Paint / Chipping -




12. Bumper / Back
Paint / Scratch / Scuff -




13. Bumper / Back
Paint / Scratch / Scuff -



14. Fender / Back Right
Paint / Scratch / Scuff -



15. Headrest / Back Left
Interior / Missing -



16. Headrest / Back Right
Interior / Missing -



17. Tailgate
Paint / Chipping -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	❗
Electric Windows	❗	Audio Equipment	✓
Other Equipments	✓		

Engine

Engine Status / EML	❗	Engine Leak Visible	✓
Engine Starts	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)