



SEAT Arosa

Arosa 1.0

VIN NO VSSZZZ6HZ3R005657

Registration Number HZ3R005657



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250922141047
Inspection Date / Place	2025-09-22 / Dello Lübeck	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	999
Engine Size	1.0	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	4
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Split folding rear seats	Remote central locking	Radio
---------------	--------------------------	------------------------	-------

Equipment Details


Air Conditioning	No
------------------	----

Wheels & Tyres


Left Rear Tyre Depth	6	Right Rear Tyre Depth	6
Left Front Tyre Depth	5	Right Front Tyre Depth	5

Cosmetic Damage

15 Schäden



2 Schäden



Component		Damage	Comments
1	Tailgate	Paint / Poor Previous Repair	
2	Fender / Front Right	Paint / Poor Previous Repair	
3	Fender / Front Left	Bodywork / Dent / Deformation	
4	Door / Front Left	Bodywork / Dent / Deformation	
5	Fender / Back Left	Bodywork / Dent / Deformation	
6	Roof	Bodywork / Dent / Deformation	
7	Fender / Back Right	Bodywork / Dent / Deformation	
8	Door / Front Right	Bodywork / Dent / Deformation	
9	Fender / Front Left	Paint / Corrosion	
10	Windshield / Front	Paint / Chipping	
11	Door / Front Left	Paint / Chipping	
12	Bumper / Back	Paint / Scratch / Scuff	


13	Bumper / Back	Paint / Scratch / Scuff
14	Fender / Back Right	Paint / Scratch / Scuff
15	Headrest / Back Left	Interior / Missing
16	Headrest / Back Right	Interior / Missing
17	Tailgate	Paint / Chipping




1. Tailgate
Paint / Poor Previous Repair -




2. Fender / Front Right
Paint / Poor Previous Repair -




3. Fender / Front Left
Bodywork / Dent / Deformation -




4. Door / Front Left
Bodywork / Dent / Deformation -



5. Fender / Back Left
Bodywork / Dent / Deformation -



6. Roof
Bodywork / Dent / Deformation -



7. Fender / Back Right
Bodywork / Dent / Deformation -



8. Door / Front Right
Bodywork / Dent / Deformation -



9. Fender / Front Left
Paint / Corrosion -



10. Windshield / Front
Paint / Chipping -



11. Door / Front Left
Paint / Chipping -




12. Bumper / Back
Paint / Scratch / Scuff -




13. Bumper / Back
Paint / Scratch / Scuff -



14. Fender / Back Right
Paint / Scratch / Scuff -



15. Headrest / Back Left
Interior / Missing -



16. Headrest / Back Right
Interior / Missing -



17. Tailgate
Paint / Chipping -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	❗
Electric Windows	❗	Audio Equipment	✓
Other Equipments	✓		

Engine

Engine Status / EML	❗	Engine Leak Visible	✓
Engine Starts	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)