



SEAT Ibiza

Ibiza SC 1.6 16V

VIN NO VSSZZZ6JZ9R124102
Registration Number JZ9R124102



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-06-01	2	2	293748 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-04-03	293238	2009-04-27	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926100457
Inspection Date / Place	2025-09-26 / ARS Altmann AG Riedstadt	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	157
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Alloys wheels	Remote adjusting wing mirrors	Stability control
Leather steering wheel	Airbag Status	Anti-lock braking	Remote central locking
CD Player	Radio		

Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	2	Extra Wheel - 2 Tyre Depth	2
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

	Component	Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Hood	Bodywork / Dent / Dent	
3	Windshield / Front	Paint / Chipping	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Rim / Front Left	Out of Bodywork / Scratch	
6	Door / Front Left	Bodywork / Dent / Dent	
7	Roof	Bodywork / Dent / Dent	
8	Seat / Front Left	Interior / Ripped	
9	Fender / Back Left	Paint / Scratch / Scuff	
10	Fender / Back Left	Bodywork / Dent / Dent	
11	Tailgate	Bodywork / Dent / Dent	
12	Tailgate	Bodywork / Dent / Dent	
13	Tailgate	Bodywork / Dent / Dent	
14	Bumper / Back	Paint / Scratch / Scuff	
15	Rear Window / Back	Glass Break / Scratch / Scratch	
16	Bumper / Back	Paint / Scratch / Scuff	
17	Fender / Back Right	Bodywork / Dent / Dent	
18	Rim / Back Right	Out of Bodywork / Scratch	
19	Fender / Back Right	Paint / Scratch / Scuff	
20	Door / Front Right	Bodywork / Dent / Dent	
21	Rocker Panel / Center Right	Bodywork / Dent / Dent	
22	Door / Front Right	Bodywork / Dent / Dent	
23	Rim / Front Right	Out of Bodywork / Scratch	
24	Fender / Front Right	Bodywork / Dent / Dent	
25	Bumper / Front	Bodywork / Dent / Dent	



1. Hood
Bodywork / Dent / Dent -



2. Hood
Bodywork / Dent / Dent -



3. Windshield / Front
Paint / Chipping -



4. Bumper / Front
Paint / Scratch / Scuff -



5. Rim / Front Left
Out of Bodywork / Scratch -



6. Door / Front Left
Bodywork / Dent / Dent -




7. Roof
Bodywork / Dent / Dent -




8. Seat / Front Left
Interior / Ripped -




9. Fender / Back Left
Paint / Scratch / Scuff -



10. Fender / Back Left
Bodywork / Dent / Dent -



11. Tailgate
Bodywork / Dent / Dent -



12. Tailgate
Bodywork / Dent / Dent -



13. Tailgate
Bodywork / Dent / Dent -



14. Bumper / Back
Paint / Scratch / Scuff -



15. Rear Window / Back
Glass Break / Scratch / Scratch -




16. Bumper / Back
Paint / Scratch / Scuff -




17. Fender / Back Right
Bodywork / Dent / Dent -




18. Rim / Back Right
Out of Bodywork / Scratch -




19. Fender / Back Right
Paint / Scratch / Scuff -



20. Door / Front Right
Bodywork / Dent / Dent -




21. Rocker Panel / Center Right
Bodywork / Dent / Dent -



22. Door / Front Right
Bodywork / Dent / Dent -



23. Rim / Front Right
Out of Bodywork / Scratch -



24. Fender / Front Right
Bodywork / Dent / Dent -



25. Bumper / Front
Bodywork / Dent / Dent -

Mechanical Condition

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓

Gearbox

Gear Box	✓
----------	---

Equipments Test

Other Equipments	✓	Main & Spare Keys Functioning	✓
Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Fume Quantity	✓	Engine Noise	✓
The Gears Scratch / Skip / Abnormal Operation	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
Clutch			
Clutch Functioning	✓		
General			
Test Driven Status	✓		

- ✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
- ! *Damages or malfunction detected that requires repairs by the buyer*
- NA *Not applicable*
- ☐ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)