



SEAT Ibiza Ibiza 1.2 12V

VIN NO VSSZZZ6LZ5R055672

Registration Number LZ5R055672



MOT Date

2025-04-01

Last Service



Number of Owners

4

Last Service Mileage



Number of Keys

2

First Registration Date

2005-03-23

Odometer Reading

209079 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250610141830
Inspection Date / Place	2025-06-10 / SULOJA Brackel	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau/schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	142
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			





Equipment

Airbag Status	Anti-lock braking	Remote central locking	LED Headlamps
Alloys wheels	Headlamp wash/wipe	Stability control	Radio


Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	15
------------------	-----	------------------	----


Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

23 Schäden




2 Schäden



5/12 - Report Number P20250610141830

14	Side Panel / Back Right	Paint / Corrosion
15	Door / Front Right	Paint / Scratch / Scuff
16	Rocker Panel / Center Right	Bodywork / Dent / Dent
17	Rocker Panel / Center Right	Paint / Corrosion
18	Fender / Front Right	Paint / Corrosion
19	Fender / Front Right	Paint / Scratch / Scuff
20	Corner Bumper / Front Left	Paint / Corrosion
21	Corner Bumper / Front Left	Paint / Scratch / Scuff
22	Hood	Bodywork / Dent / Hail Area
23	Hood	Paint / Corrosion
24	Corner Bumper / Front Right	Paint / Scratch / Scuff
25	Glovebox	Interior / Dysfunctional



1. Seat / Back Left
Interior / Holed -



2. Fender / Front Left
Bodywork / Dent / Dent -




3. Fender / Front Left
Paint / Corrosion -




4. Door / Front Left
Paint / Corrosion -



5. Door / Front Left
Paint / Scratch / Scuff -




6. Door / Front Left
Paint / Scratch / Scuff -



7. Door / Front Left
Paint / Scratch / Scuff -



8. Side Panel / Back Left
Paint / Corrosion -



9. Bumper / Back
Paint / Scratch / Scuff -




10. Bumper / Back
Paint / Corrosion -



11. Corner Bumper / Back Right
Paint / Scratch / Scuff -




12. Corner Bumper / Back Right
Paint / Corrosion -




13. Side Panel / Back Right
Paint / Scratch / Scuff -



14. Side Panel / Back Right
Paint / Corrosion -



15. Door / Front Right
Paint / Scratch / Scuff -



16. Rocker Panel / Center Right
Bodywork / Dent / Dent -



17. Rocker Panel / Center Right
Paint / Corrosion -



18. Fender / Front Right
Paint / Corrosion -



19. Fender / Front Right
Paint / Scratch / Scuff -




20. Corner Bumper / Front Left
Paint / Corrosion -



21. Corner Bumper / Front Left
Paint / Scratch / Scuff -



22. Hood
Bodywork / Dent / Hail Area -



23. Hood
Paint / Corrosion -



24. Corner Bumper / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
AC / Heating System	!	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Engine Noise	!	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
General			
Test Driven Status	✓		
Steering Wheel			
Steering Noise / Anomaly !			
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)