



## SEAT Ibiza Ibiza 1.2 12V

VIN NO VSSZZZ6LZ8R114032

Registration Number LZ8R114032



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



### Inspection Report Summary

|                         |                                    |                |                 |
|-------------------------|------------------------------------|----------------|-----------------|
| Customer                | BCA Online                         | Report Number  | P20250909141951 |
| Inspection Date / Place | 2025-09-09 / Dello Neumünster-Nord | Cosmetic Grade | 5               |

### Vehicle Summary

|                    |         |                        |        |
|--------------------|---------|------------------------|--------|
| Vehicle Condition  | Runner  | VAT Type               | Margin |
| Fuel Type          | Petrol  | Road Worthy            | Yes    |
| Colour             | Grey    | Engine Size (cc)       | 1198   |
| Engine Size        | 1.2     | No of Doors            | 3      |
| Body Type          | Sedan   | Drive Train            | Front  |
| Seat Colour        |         | No of Seats            | 5      |
| Seat Covering Name | Schwarz | Seat Covering          | Cloth  |
| Charging Cables    |         | NEDC CO2 Rating (q/km) | 138    |
| Gearbox Type       | Manual  |                        |        |

### Vehicle History & Documents

|                        |                      |                      |    |
|------------------------|----------------------|----------------------|----|
| Service Book Available | Full Service History | Next Service Mileage | km |
| Previous Usage         |                      | Imported             | No |
| Manufacturer Warranty  |                      |                      |    |







Equipment

|                 |               |                   |                   |
|-----------------|---------------|-------------------|-------------------|
| Trip Computer   | Airbag Status | Auxiliary Socket  | CD Player         |
| Radio           | USB Socket    | Anti-lock braking | Stability control |
| Central locking |               |                   |                   |


Equipment Details

|                  |    |              |    |
|------------------|----|--------------|----|
| Air Conditioning | No | Seat Heating | No |
|------------------|----|--------------|----|


Wheels & Tyres

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 3 | Left Front Tyre Depth | 3 |
| Right Rear Tyre Depth  | 3 | Left Rear Tyre Depth  | 3 |

## 18 Schäden



### 3 Schäden

6/13 - Report Number P20250909141951

|    |                                     |                             |
|----|-------------------------------------|-----------------------------|
| 13 | Fender / Back Right                 | Paint / Scratch / Scuff     |
| 14 | Door / Front Right                  | Bodywork / Dent / Dent      |
| 15 | Mirror / Front Right                | Paint / Scratch / Scuff     |
| 16 | Fender / Front Left                 | Paint / Corrosion           |
| 17 | Roof                                | Bodywork / Dent / Hail Area |
| 18 | Seat / Front Left                   | Interior / Ripped           |
| 19 | Steering Wheel / Front              | Interior / Worn - out       |
| 20 | Dashboard / Front                   | Interior / Not Working      |
| 21 | Windshield Wiper Blade / Front Left | Bodywork / Breakage / Crack |




1. Door / Front Left  
Paint / Poor Previous Repair -



2. Fender / Back Left  
Paint / Poor Previous Repair -



3. Fender / Front Right  
Paint / Poor Previous Repair -



4. Hood  
Bodywork / Dent / Hail Area -




5. Hood  
Paint / Corrosion -



6. Bumper / Front  
Paint / Scratch / Scuff -



7. Fender / Back Left  
Paint / Poor Previous Repair -



8. Fender / Back Left  
Bodywork / Dent / Dent -



9. Fender / Back Left  
Paint / Scratch / Scuff -




10. Bumper / Back  
Bodywork / Breakage / Crack -




11. Bumper / Back  
Paint / Scratch / Scuff -



12. Fender / Back Right  
Paint / Scratch / Scuff -



13. Fender / Back Right  
Paint / Scratch / Scuff -




14. Door / Front Right  
Bodywork / Dent / Dent -




15. Mirror / Front Right  
Paint / Scratch / Scuff -



16. Fender / Front Left  
Paint / Corrosion -



17. Roof  
Bodywork / Dent / Hail Area -



18. Seat / Front Left  
Interior / Ripped -



19. Steering Wheel / Front  
Interior / Worn - out -



20. Dashboard / Front  
Interior / Not Working -



21. Windshield Wiper Blade / Front Left  
Bodywork / Breakage / Crack -

## Mechanical Condition

### Control Lights

|                                 |   |                                              |   |
|---------------------------------|---|----------------------------------------------|---|
| Display Defect                  | ✓ | Service Light                                | ! |
| ABS Warning Light               | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light            | ✓ | Oil Pressure Warning Light                   | ✓ |
| Brake Warning Light             | ✓ | Power Steering Warning Light                 | ✓ |
| Alternator / Battery            | ✓ | No Dashboard Lights                          | ✓ |
| Tire Pressure Monitoring System | ✓ |                                              |   |

### Equipments Test

|                     |   |                  |   |
|---------------------|---|------------------|---|
| Central Locking     | ! | Audio Equipment  | ! |
| AC / Heating System | ✓ | Other Equipments | ✓ |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ! |
| Engine Starts       | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ! |
|--------------|---|---------------|---|

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly 

Engine

Engine Noise  The Gears Scratch / Skip / Abnormal Operation 

Fume Quantity  Power Loss 

Brake

Brake System Anomaly 

General

Test Driven Status 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)