



# SEAT Ibiza

## Ibiza 1.0 EcoTSI S&S

VIN NO VSSZZKJZJR003473  
Registration Number JZJR003473



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-07-01	3	2	121112 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2022-05-05	82871	2017-06-09	Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250925111914
Inspection Date / Place	2025-09-25 / BCA Heidenheim	Cosmetic Grade	2

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Champagne	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	108
Gearbox Type	Manual		

### Vehicle History & Documents



Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











Equipment

USB Socket	Alloys wheels	Anti-lock braking	Auxiliary Socket
Cruise control	Front fog lamps	Remote adjusting wing mirrors	Reversing Camera
Split folding rear seats	Electrically folding wing mirrors	Leather steering wheel	Radio
Airbag Status	AndroidAuto	AppleCarPlay	Bluetooth telephone interface
Digital Radio	Front parking sensors	Remote central locking	Satellite navigation
Stability control	Keyless Entry	LED Headlamps	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	2	Left Front Tyre Depth	2
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

10 Schäden



3 Schäden



Component		Damage	Comments
1	Seat / Front Right	Interior / Dirty	
2	Seat / Back Right	Interior / Dirty	
3	Rim / Back Right	Out of Bodywork / Scratch	
4	Luggage Space Cover / Back	Interior / Missing	
5	Windshield / Front	Glass Break / Impact	
6	Bumper / Back	Paint / Scratch / Scuff	
7	Bumper / Front	Paint / Scratch / Scuff	
8	Side Panel / Back Left	Bodywork / Dent / Dent	
9	Bumper / Front	Paint / Scratch / Scuff	
10	Rim / Front Right	Out of Bodywork / Scratch	
11	Rim / Back Right	Out of Bodywork / Scratch	
12	Door / Back Right	Bodywork / Dent / Dent	

13 Bumper / Back

Paint / Scratch / Scuff





1. Seat / Front Right  
Interior / Dirty -



2. Seat / Back Right  
Interior / Dirty -



3. Rim / Back Right  
Out of Bodywork / Scratch -



4. Luggage Space Cover / Back  
Interior / Missing -




5. Windshield / Front  
Glass Break / Impact -




6. Bumper / Back  
Paint / Scratch / Scuff -





7. Bumper / Front  
Paint / Scratch / Scuff -



8. Side Panel / Back Left  
Bodywork / Dent / Dent -




9. Bumper / Front  
Paint / Scratch / Scuff -




10. Rim / Front Right  
Out of Bodywork / Scratch -



11. Rim / Back Right  
Out of Bodywork / Scratch -



12. Door / Back Right  
Bodywork / Dent / Dent -



13. Bumper / Back  
Paint / Scratch / Scuff -



## Mechanical Condition

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	⚠

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Equipments Test

AC / Heating System	✓	Central Locking	✓
Main & Spare Keys Functioning	⚠	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓		

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)