



Seat Arona: G078NH

Vinnnumber:	VSSZZZKJZLR075895	Versionname:	Arona 1.0 TSI 85kW FR Business Intense DSG-7
First Registrationdate:	6/11/2019	Fiscalpower:	
Expertise Mileage:	116787	Power Kw:	85
Bodytype:		Body colour:	Magnetic Tech metallic lak/dak Midnight
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	1089
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors

Degree of wear

205/55/17/95 H			
Winter tyres:	Fr.L.	Continental: 7,1 mm	Fr.R.
	Re.L.	Continental: 8,9 mm	Re.R.
			Continental: 7,1 mm
			Continental: 8,3 mm
Tyre profile depth FL			7.1
Tyre profile depth FR			7.1
Tyre profile depth RL			8.9
Tyre profile depth RR			8.3
Tyre size FL			205/55 R 17 95 H
Tyre size FR			205/55 R 17 95 H
Tyre size RL			205/55 R 17 95 H
Tyre size RR			205/55 R 17 95 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment


Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Stain, Cleaning





Door RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Roof pillar R, Scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Stone chip(s), Repair and paint (complete)

