



Seat Arona: K575DS

Vinnumber:	VSSZZZKJZMR036984	Versionname:	Arona 1.0 TSI 85kW Style Business Intense
First Registrationdate:	30/11/2020	Fiscalpower:	
Expertise Mileage:	117121	Power Kw:	85
Bodytype:		Body colour	Magnetic Tech metallic lak
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	226
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 96 / H / Aluminium	6,3 mm	Vredestein	Winter
	Right	205 / 60 / 16 / 96 / H / Aluminium	7,3 mm	Vredestein	Winter
Rear	Left	205 / 60 / 16 / 96 / H / Aluminium	8,0 mm	Vredestein	Winter
	Right	205 / 60 / 16 / 96 / H / Aluminium	7,9 mm	Vredestein	Winter

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Stain, Cleaning



Door RL, Dent(s), Repair and paint (complete)





Wing RL, Dent(s), Repair and paint (complete)



Door FL, Bad repair, Repair and paint (complete)



Bonnet, Chemical polution, Polish



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Roof pillar R, Dent(s), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Smart repair



Bumper RM, Scratch(es), Smart repair

