



Seat Arona: N715VD

Vinnnumber:	VSSZZKJZNR046783	Versionname:	Arona 1.0 TSI 70kW Reference
First Registrationdate:	21/01/2022	Fiscalpower:	
Expertise Mileage:	161168	Power Kw:	70
Bodytype:		Body colour	Midnight Black metallic lak
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	707
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	1	Telephone equipment
Number keys remote	1	Luggage cover
Manual climate control		Headlights Xenon/LED/Laser
Windows electric F		Hook
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 61 / 16 / 92 / H / Aluminium	3,0 mm	Goodyear	Summer
	Right	205 / 61 / 16 / 92 / H / Aluminium	3,2 mm	Goodyear	Summer
Rear	Left	205 / 61 / 16 / 92 / H / Aluminium	3,2 mm	Goodyear	Summer
	Right	205 / 61 / 16 / 92 / H / Aluminium	3,0 mm	Goodyear	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



User's manual, Missing, Replace

No pictures to display

Ignition key, Missing, Replace

No pictures to display

Interior, Stain, Cleaning



Seat cover R, Worn, Replace



Roof pillar L, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Dent(s) and scratch(es), Replace



Bonnet, Stone chip(s), Repair and paint (complete)



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Wing RR, Bad repair, Repair and paint (complete)

