


Vehicle details

VIN	VSSZZKJZ NR110779	Brand	SEAT	Maintenance date	-
Licence Plate	E283DA	Model	IBIZA 1.0 59kw Reference 59KW	Maintenance mileage	-
Registration date	07/09/2022	Year	1000	Exterior Color	Red Solid
Odometer	137 904 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	01/09/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	06/11/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Xenon projectors	✓

Removable element

--	--

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres

Exterior

2		Part	Bumper	3		Part	Roof
		Position	Front			Position	-
4		Damages	Scatched	5		Damages	Hail damaged
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair
		Part	Tailgate / Boot door			Part	Bumper
		Position	-			Position	Back
		Damages	Dent & Chips			Damages	Scatched
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair



DEKRA Automotive Solutions

<b>6</b>		Part	Rear light (wing)
		Position	Back right
		Damages	Scratched
		Severity	-
		Repair mode	Replace

Interior damage

<b>1</b>		Part	Interior cleaning
		Position	-
		Damages	Not carried out
		Severity	-
		Repair mode	Lumpsum

Others

<b>7</b>		Part	Paint preparation
		Position	-
		Damages	-
		Severity	-
		Repair mode	Paintworks

<b>8</b>		Part	Paint preparation
		Position	-
		Damages	-
		Severity	-
		Repair mode	Plastic paint