



## Seat Leon (UKL): 2DUA927

|                                   |                  |                        |                                |
|-----------------------------------|------------------|------------------------|--------------------------------|
| Vinnumber:                        | VSSZZKL3PR046774 | Versionname:           | Leon ST Move 1.0TSi 90pk/cv 5p |
| First Registrationdate:           | 26/06/2023       | Fiscalpower:           |                                |
| Expertise Mileage:                | 72705            | Power Kw:              | 66                             |
| Bodytype:                         |                  | Type of rims (mounted) | Aluminium                      |
| Gearbox:                          | MAN 5 VIT        |                        |                                |
| Transmission:                     |                  |                        |                                |
| Fueltype:                         |                  |                        |                                |
| Maintenance                       | OK               |                        |                                |
| Maintenance                       | plus 18900 km    |                        |                                |
| Battery functioning               | Yes              |                        |                                |
| Type of rims (mounted)            | Aluminium        |                        |                                |
| Certificate of Conformity         | Yes              |                        |                                |
| Category                          | Passenger Car    |                        |                                |
| Registration Certificate Car (BE) | Yes              |                        |                                |

## Options

|                          |                     |                 |            |
|--------------------------|---------------------|-----------------|------------|
| Number of keys total     | 2                   | Luggage cover   |            |
| GPS                      |                     | Type of Tow bar | No Tow bar |
| Type of Maintenance book | Digital maintenance |                 |            |
| Type of GPS storage      | HD                  |                 |            |


## Tyres

| 205/55/16/94 V        |       |                  |       |                  |
|-----------------------|-------|------------------|-------|------------------|
| Summer tyres:         | Fr.L. | Vredestein: 3 mm | Fr.R. | Vredestein: 3 mm |
|                       | Re.L. | Vredestein: 5 mm | Re.R. | Vredestein: 5 mm |
| Tyre profile depth FL |       |                  |       | 3.0              |
| Tyre profile depth FR |       |                  |       | 3.0              |
| Tyre profile depth RL |       |                  |       | 5.0              |
| Tyre profile depth RR |       |                  |       | 5.0              |
| Tyre size FL          |       |                  |       | 205/55 R 16 94 V |
| Tyre size FR          |       |                  |       | 205/55 R 16 94 V |
| Tyre size RL          |       |                  |       | 205/55 R 16 94 V |
| Tyre size RR          |       |                  |       | 205/55 R 16 94 V |
| Tyre type FL          |       |                  |       | All seasons      |
| Tyre type FR          |       |                  |       | All Seasons      |
| Tyre type RL          |       |                  |       | All seasons      |
| Tyre type RR          |       |                  |       | All Seasons      |
| Tyre make FL          |       |                  |       | 2480             |
| Tyre make FR          |       |                  |       | 2480             |
| Tyre make RL          |       |                  |       | 2480             |
| Tyre make RR          |       |                  |       | 2480             |

## Assistance equipment

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 0   |            |     |
| Number of charging cables (rapid charge) | 0   |            |     |

MOT certificate, Missing, Replace



Sunblind, Broken, Replace



Seat cover FL, Stain, Acceptable



Brand badge F, Worn, Acceptable



Bumper grille, Scratch(es), Replace



Alloy rim FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Door RL, Repaired, Check



Wing RL, Repaired, Check



Tailgate / Boot, Dent(s), Acceptable



Bumper trim R, Scratch(es), Acceptable



Wing RR, Dent(s), Acceptable



Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace

