

Damage Review



Jobnr	131436
Fleet	BRENT N
Lease	
Driver	Bestuurder
Location	
Date	08-07-2025
Date Hour	11:48

Make	SEAT
Model	LEON
Type	
Licenseplate	R047305
Chassisnr	VSSZZZKL6PR047305
Color	Zilver
First Registration	
Mileage	39655
VP/VU	VP
Fuel	petrol
Fuel Level	8/8
Total Keys	1
Seats MVP	5

Check			
COC	No	Safety Kit	Yes
Registration doc	No	Triangle	Yes
Insurance doc	No	GPS	No
Manual	No	Fuel Card	No
Service book	No	Alarm	No
Fire extinguisher	Yes	Service Needed	No
Rear Shelf	No		

Remarks

Batterij sleutel vervangen.

<u>Financial Result Damage Appraisal</u>		
	Acceptable Total	0,00 €
	Not Acceptable Total	1345,97 €
	Depreciation	0 %
	Not Acceptable Depreciated Total	1345,97 €
	Total Damages	1345,97 €
	Total Damages (Depreciation incl.)	1345,97 €
		(bedragen excl. BTW)

Signatures


Damage advisor

Client
BRENT N



interior	2 Dashboard	STEERING WHEEL	NA	N comf / out of order	Replace	€ 487.3
exterior	30 Extra	STICKERS	NA	Remainder stickers	Remove stickers	€ 25
exterior	1 BumperF	SPOILER	NA	scratch	Replace	€ 151.93
exterior	22 MirrorR	CAP PAINTED	NA	scratch	Paint	€ 85
exterior	18 WingRR	WING RR	NA	scratch + dent	SR - PDR	€ 109.5
exterior	13 BumperR	BUMPER REAR	NA	scratch	Paint	€ 395
interior	19 CoverBonnet	COVER BONNET	NA	scratch	Replace	€ 92.24
exterior	3 Bonnet	BONNET	A	stone chipping	Paint	€ 0
exterior	1 BumperF	BUMPER FRONT	A	stone chipping	Paint	€ 0
interior	30 Missing	2ND KEY	A	missing	Check	€ 0

General Pictures





Damage Appraisal



interior	2 Dashboard	STEERING WHEEL	NA N comf / out of order	Replace	€ 487.3
----------	-------------	----------------	--------------------------	---------	---------

Combinatieschakelaar te vervangen.



exterior	30 Extra	STICKERS	NA Remainder stickers	Remove stickers	€ 25
----------	----------	----------	-----------------------	-----------------	------



exterior	1 BumperF	SPOILER	NA scratch	Replace	€ 151.93
----------	-----------	---------	------------	---------	----------



exterior	22 MirrorR	CAP PAINTED	NA scratch	Paint	€ 85
----------	------------	-------------	------------	-------	------




exterior	18 WingRR	WING RR	NA scratch + dent	SR - PDR	€ 109.5
----------	-----------	---------	-------------------	----------	---------

+ polieren.



exterior	13 BumperR	BUMPER REAR	NA scratch	Paint	€ 395
----------	------------	-------------	------------	-------	-------



interior	19 CoverBonnet	COVER BONNET	NA scratch	Replace	€ 92.24
----------	----------------	--------------	------------	---------	---------




exterior	3 Bonnet	BONNET	A stone chipping	Paint	€ 0
----------	----------	--------	------------------	-------	-----



exterior	1 BumperF	BUMPER FRONT	A stone chipping	Paint	€ 0
----------	-----------	--------------	------------------	-------	-----



interior	30 Missing	2ND KEY	A missing	Check	€ 0
----------	------------	---------	-----------	-------	-----



Vehicle Condition	Interior: clean
	Exterior: clean

Tyres			
Type	Summer	Flat/RSC	No
Spare Tyre	No	Repair Kit	Yes
Front Left			
Profile	6	Side Damage	No
Front Right			
Profile	6	Side Damage	No
Rear Left			
Profile	6	Side Damage	No
Rear Right			
Profile	6	Side Damage	No