

VSSZZZKLZNR062543

CUPRA Leon Leon 2.0 TSI DSG



TECHNICAL CONDITION

Engine	Brakes	Steering
Engine starts	Brake operation	Sounds normal
Engine operation	Clutch Clutch operation Idle sounds normal Clutch biting point	Gear Box Automatic shift Manual shif Warning light OK
Engine compartment dry (oil)		
Fume quantity		
Sounds normal		

COMPLAINT NOTE

The technical check includes a visual check of the vehicles without removal of any components.
The condition of the mechanical components cannot be rated.

LEVELS

Coolant fluid
Brakes fluid

EQUIPMENT TEST

Electric windows test
Audio equipment
Navigation equipment
AC / Heating system
Central lock system test

TYRES

Profile depths

FL 6 mm FR 6 mm

BR 7 mm BL 7 mm

Additional tyre profil depths

A B

C D

CONTROL LIGHTS

Dashboard
ABS
Oil
Airbag
Engine
Brakes
Steering
DPF
Diesel heaters
Traction control / ESP / Stability control
4x4
Alternator / Battery



No defects recognizable, good condition or positive tests based on vehicle's age and mileage.



Registered damage that needs to be repaired by the buyer.



Not verifiable.