MACADAM

Opel Movano (Segm. B3): 2ECV019

Vinnumber:	**VXEYCCPFCPG028526**	Versionname:	**Movano L3H2 3500 Light 2.2 TurboD 165pk/cv**
First Registrationdate:	**31/08/2023**	Fiscalpower:	
Expertise Mileage:	**150478**	Power Kw:	**121**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:			
Maintenance	**OK**		
Maintenance	**geen melding db**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Light Commercial Vehicle**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**Tow bar fixed**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/79/15/109 C**			
	Fr.L.	**Continental: 5 mm**	Fr.R.	**Continental: 5 mm**
	Re.L.	**Continental: 7 mm**	Re.R.	**Continental: 7 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**7.0**
Tyre profile depth RR	**7.0**
Tyre size FL	**215/79 R 15 109 C**
Tyre size FR	**215/79 R 15 109 C**
Tyre size RL	**215/79 R 15 109 C**
Tyre size RR	**215/79 R 15 109 C**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**0**		

Interior, Chemical polution, Forfeit

Interior covering A pillar L, Chemical polution, Smart repair

Bumper F, Scratch(es), Smart repair

Step L, Bad repair, Repair and paint (complete)

Tyre RL, Tear, Replace

Door FL, Dent(s), Repair and paint (complete)

Wing RL, Dent(s), Repair and paint (complete)

Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

Outside rear-view mirror R, complete, Broken, Replace