

Inspected by: Mik Kieft



| Brand: | Opel | Mileage(km): | 119995 |
|------------------------------------|------------------------|----------------------|------------|
| Model: | Corsa-E | Number of doors: | 5 |
| Model type: | Elegance 50 kWh 3 FASE | Vehicle length (cm): | |
| License plate: | J375VT | Vehicle width (cm): | |
| Report code: | 3489 | Vehicle height (cm): | |
| Chassis number: | VXKUHZKXZL4383489 | Vehicle body type: | |
| Type of vehicle: | Luxury | Traction: | Front |
| First int. reg.: | 30/10/2020 | Power(kw): | 100 |
| First NL reg.: | 30/10/2020 | Transmission | Automatic |
| Color: | Blue Metallic | Number of gears | |
| Weight (kg)(kg): | 1530 | Displacement(cc): | |
| Empty weight(kg): | 1430 | Number of cylinders: | |
| Wheelbase (cm)(cm): | 254 | Fuel type: | Electric |
| Top speed (km/h): | 150 | Fuel tank capacity: | |
| Cons. in the city (I/100 km): | | EU category: | |
| Cons. outside the city (I/100 km): | | Energy label: | Α |
| Avarage consumption (I/100 km): | | NL Tax Rate %: | 8 |
| Acceleration (s): | 8.1 | CO2 (q/km): | 1 |
| Cargo space (I): | 1530 | Nb. of Axles: | 2 |
| Perm. max weight (kg): | 1920 | APK date: | 30/10/2026 |

opties 🚓

- Alloy wheels
- Digital dashboard
- Daytime running lights
- Licht Sensor
- bots waarschuwing systeem
- ABS
- Airbag(s)
- Audio
- Fog lamps
- Start/stop system
- Power steering
- Multifunctional steering wheel
- Remote central locking
- Metallic finish
- LED headlights
- Privacy glass

- Rain sensor
- Rear wiper
- Rear view camera
- Rear parking sensors
- Front parking sensors
- Rear-seat folding (unequal parts) $[\checkmark]$
- Luggage cover
- Charging cable 220V
- USB connection
- \ \ \ Bluetooth streaming DAB+
- Bluetooth car kit
- Radio
- WiFi
- SISISIS Cruise control (adaptive)
- Cruise control

- Climate control
- Climate control (analog)
- Climate control (digital)
- Climate control (L/R separated)
- Large screen navigation
- Keyless entry
- Keyless start/stop
- Electrically operated rear windows
- Electrically operated front windows
- Electrically folding mirrors
- Electrically adjustable mirrors
- Central armrest front
- Audio control on the steering wheel
- Leather steering wheel
- Lane assistance
- Pedestrian safety system

🗱 Tires

| Tire | Tire | Wheel | Tire size: | Tire brand: | Tire profile depth (mm): |
|------------------|--------|-------|------------|-------------|--------------------------|
| position: | type: | type: | | | |
| Tire left front | Summer | Alloy | 205/45 R17 | Michelin | 3 |
| Tire left rear | Summer | Alloy | 205/45 R17 | Continental | 6 |
| Tire right front | Summer | Alloy | 205/45 R17 | Michelin | 3 |
| Tire right rear | Summer | Allov | 205/45 R17 | Continental | 6 |

Additional information

| Additional information | | | |
|------------------------|----------------------------------|------------------------|----------------------------------|
| No. of keys: | 2 Luxury key Instruction booklet | | ✓ Airco works |
| Interior color: | Black | Maintenance booklet: | ⊘ Odorless |
| Upholstery: | Half stof/leder | | Clean inside (Interior is clean) |
| No. of seats: | 5 | Stamp date: | ☑ Display ok |
| No. of headrests: | 5 | Last turn mileage(km): | Vehicle special usage (None) |

▲ Cleaning

Clean inside (Interior is clean)


Damages



Front left rim - Scratch



Rear left door - Scratch



Not acceptable

Rear left rim - Scratch



Rear right rim - Scratch



Front right rim - Scratch

Damages

☼Extra options

Acceptable





































































AUTOF CTOR