



Opel Corsa: K016KT

Vinnnummer:	VXXKUPMHDL4465162	Versionname:	Corsa 1.2 55kW Edition
First Registrationdate:	25/02/2021	Fiscalpower:	
Expertise Mileage:	57563	Power Kw:	55
Bodytype:		Body colour:	Diamond Black metallic
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Petrol	Parking lot:	197
Number of seats:	5		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	1	Luggage cover
Manual climate control		Rear parking sensors
Windows electric F		
Radio multimedia		

Degree of wear

185/65/15/88 H				
Summer tyres:	Fr.L.	Continental: 5,5 mm	Fr.R.	Continental: 8,6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 3,1 mm
Tyre profile depth FL				5.5
Tyre profile depth FR				8.6
Tyre profile depth RL				4.0
Tyre profile depth RR				3.1
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Chemical pollution, Cleaning



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Chemical polution, Cleaning

