


## Vehicle details

|                   |                    |              |                                        |                              |             |
|-------------------|--------------------|--------------|----------------------------------------|------------------------------|-------------|
| VIN               | VXKUPMHMD N4396263 | Brand        | OPEL                                   | Maintenance date             | -           |
| Licence Plate     | R8-36-XP           | Model        | CORSA 1.2 EDITION 55KW<br>5d Onze Deal | Maintenance<br>mileage       | -           |
| Registration date | 15/12/2022         | Year         | 2022                                   | Exterior Color               | Black Solid |
| Odometer          | 44 108 km          | Engine size  | 1199                                   | interior Color               | Grey        |
| Fuel              | Petrol             | Body Type    | -                                      | Next technical<br>inspection | -           |
| Seats             | -                  | Transmission | Manual                                 | CO2                          | -           |
| Doors             | 5                  | Gears        | 5                                      |                              |             |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 21/08/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                         |   |
|-------------------------|---|
| Manual air-conditioning | ✓ |
| Cruise control          | ✓ |
| GPS system              | ✓ |
| Alloy wheel rims        | ✓ |
| Central locking         | ✓ |
| Electric windows        | ✓ |
| Park Distance Control   | ✓ |
| Audio System            | ✓ |


## Removable element

|                   |   |
|-------------------|---|
| Spare wheel kit   | ✓ |
| Rear parcel shelf | ✓ |

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Key                     | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres



## Exterior

1



|             |                  |
|-------------|------------------|
| Part        | Roof             |
| Position    | -                |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | Lumpsum repair   |

2



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Back right         |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

3



|             |                    |
|-------------|--------------------|
| Part        | Bumper             |
| Position    | Back               |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Repair             |

4



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Back left          |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

5



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Front left         |
| Damages     | Dent & Chips       |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |