


Vehicle details

VIN	VXKUPHNEK N4452654	Brand	OPEL	Maintenance date	-
Licence Plate	S5-07-VX	Model	CORSA 1.2 TURBO LEVEL 2 74KW 5d	Maintenance mileage	-
Registration date	26/04/2023	Year	2023	Exterior Color	Silver Metallic
Odometer	56 101 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	08/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres



Exterior


1



● ● ● ● ●

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

2



● ● ● ● ● ●

Part	Wing
Position	Back right
Damages	Dented
Severity	-
Repair mode	Repair

3



● ● ● ● ● ●

Part	Door
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

4



● ●

Part	Bonnet
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

5



● ● ● ● ● ●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

6



● ●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



● ●

Part	Fuel filler flap
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

8



● ●

Part	Wing
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

Interior damage

9  ● ●	<table> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scratched	Severity	-	Repair mode	Smart Repair
Part	Interior tailgate lining										
Position	-										
Damages	Scratched										
Severity	-										
Repair mode	Smart Repair										