


## Vehicle details

|                   |                    |              |                                 |                           |                |
|-------------------|--------------------|--------------|---------------------------------|---------------------------|----------------|
| VIN               | VXKUPHNEK N4452889 | Brand        | OPEL                            | Maintenance date          | -              |
| Licence Plate     | S5-43-VX           | Model        | CORSA 1.2 TURBO LEVEL 2 74KW 5d | Maintenance mileage       | -              |
| Registration date | 26/04/2023         | Year         | 2023                            | Exterior Color            | Black Metallic |
| Odometer          | 74 079 km          | Engine size  | 1199                            | interior Color            | Grey           |
| Fuel              | Petrol             | Body Type    | -                               | Next technical inspection | -              |
| Seats             | -                  | Transmission | Manual                          | CO2                       | -              |
| Doors             | 5                  | Gears        | 6                               |                           |                |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 09/10/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| Alloy wheel rims           | ✓ |
| Tow                        | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |


## Removable element

|                   |   |
|-------------------|---|
| Spare wheel kit   | ✓ |
| Rear parcel shelf | ✓ |

## Technical Document

|                  |   |
|------------------|---|
| User manual      | ✓ |
| Warranty booklet | ✓ |
| Key              | ✓ |
| Remote key       | ✓ |

## Tyres

|                                     |                                                                                     |                                     |                                                                                      |
|-------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|--------------------------------------------------------------------------------------|
| Hankook 195/55/16 Summer 5.0 mm     |  | Hankook 195/55/16 Summer 5.0 mm     |  |
| Continental 195/55/16 Summer 4.0 mm |                                                                                     | Continental 195/55/16 Summer 4.0 mm |                                                                                      |

## Exterior

4



Part

Position

Damages

Severity

Repair mode

Windscreen

-

Stone impact

-

For info

●

●

5



Part

Position

Damages

Severity

Repair mode

Roof

-

Chemical deposit

-

Lumpsum repair

●

●

●

Interior damage

1



Part

Position

Damages

Severity

Repair mode

Interior cleaning

Front

Stained/dirty

-

Cleaning

●

●

●

2



Part

Position

Damages

Severity

Repair mode

Interior cleaning

Back

Stained/dirty

-

Cleaning

●

●

●

3



Part

Position

Damages

Severity

Repair mode

Boot carpet

Back

Stained/dirty

-

Cleaning

●

●

●