

Vehicle details

VIN	VXKUPHNKK L4365473	Brand	OPEL	Maintenance date	-
Licence Plate	J1-77-RN	Model	CORSA 1.2 TURBO GS LINE 74KW ACTI GS LINE APL 5d	Maintenance mileage	-
Registration date	30/09/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	79 239 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	06/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

2



Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

3



Part	Tailgate / Boot door
Position	Up
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4



Part	Roof
Position	-
Damages	Hail damaged
Severity	Diameter (mm) > 20
Repair mode	Repair

5



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

6



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning