


Vehicle details

VIN	VXKUPHNKK L4374646	Brand	OPEL	Maintenance date	-
Licence Plate	J1-85-SP	Model	CORSA 1.2 TURBO GS LINE 74KW ACTI GS LINE APL 5d	Maintenance mileage	-
Registration date	12/10/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	73 769 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	13/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment	
Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element	
Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document	
User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Pirelli 195/55/16 Summer 5.0 mm

Pirelli 195/55/16 Summer 5.0 mm

Pirelli 195/55/16 Summer 7.0 mm

Pirelli 195/55/16 Summer 7.0 mm

Exterior

<p>2</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Bonnet	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>3</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 16"</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 16"	Position	Back left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Bonnet																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Alloy wheel 16"																						
Position	Back left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>Up</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Tailgate / Boot door	Position	Up	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair	<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Tailgate / Boot door																						
Position	Up																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Door																						
Position	Back right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Front right	Damages	Dented	Severity	-	Repair mode	For info												
Part	Step plate																						
Position	Front right																						
Damages	Dented																						
Severity	-																						
Repair mode	For info																						

Interior damage

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning										
Position	Front										
Damages	Stained/dirty										
Severity	-										
Repair mode	Cleaning										