DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

Vehicle details

VIN	VXKUPHNKK L4401056	Brand	OPEL	Maintenance date	-
Licence Plate	J7-29-XF	Model	CORSA 1.2 TURBO EDITION 74KW ACTI Corsa 2020 APL 5	Maintenance mileage	-
Registration date	04/11/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	87 905 km	Engine size	1199	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	03/11/2025	Inspection loc.	Dekra Ayvens

Generic equipment

Manual air-conditioning	✔
Cruise control	✔
Metallic paint	✔
Central locking	✔
Electric windows	✔
Audio System	✔

Removable element

Spare wheel (wheel & tyre)	✔
Rear parcel shelf	✔

Technical Document

User manual	✔
Warranty booklet	✔
Key	✔
Remote key	✔

Tyres

Pirelli 195/55/16 Summer 6.0 mm

Pirelli 195/55/16 Summer 6.0 mm



Pirelli 195/55/16 Summer 6.0 mm

Pirelli 195/55/16 Summer 7.0 mm

Exterior

DEKRA

DEKRA Automotive Solutions

Appraisal Report

DEKRA

1

Part	Door
Position	Front left
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

3

Part	Wing
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

4

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5

Part	Bonnet
Position	-
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6

Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

7



Part	Roof
Position	-
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

Interior damage

2

Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace