

MAINTENANCE HISTORY

Generation date: 2025/11/27

Plate Number **J7-31-XR**
 Make **OPEL**
 Model **CORSA**
 Vehicle Description **1.2 TURBO ELEGANCE 74KW ACTI ELEGANCE APL 5d**

DATE	MILEAGE	TYPE	DESCRIPTION	SUPPLIER
2025/09/10	0 KM	damage	Achterzijde Diversen Achterbumper (onb) tpy, geen WBF	geen herstel Schade, ,
2024/10/21	0 KM	damage	Mistlamp Achterzijde (onb) tpy, geen WBF	Bosch Car Service Kralingen, ,
2021/01/20	0 KM	damage	Linkerzijde Portier onbekende oorzaak	Schadenet Van As Capelle a/d IJssel, ,
2025/01/16	35444 KM	repair	Koelventilator - Vastgelopen - Vervangen	Bosch Car Service Kralingen, ,
2024/10/21	33104 KM	repair	- Opel OH Groot - NVT - Uitvoeren APK icm beurt - NVT - Uitvoeren Bougie - versleten - Vervangen Int luchtfilter - versleten - Vervangen Luchtfilter -	- Bosch Car Service Kralingen, , - Bosch Car Service Kralingen, ,

			versleten - Vervangen	• Bosch Car Service Kralingen, , • Bosch Car Service Kralingen, , • Bosch Car Service Kralingen, ,
2023/11/10	21026 KM	repair	• Opel OH Klein - NVT - Uitvoeren	• Bosch Car Service Kralingen, ,
2022/11/04	8968 KM	repair	• Opel OH Klein - NVT - Uitvoeren Int luchtfilter - versleten - Vervangen	• Bosch Car Service Kralingen, , • Bosch Car Service Kralingen, ,
2021/11/16	3543 KM	repair	• Opel OH Klein - NVT - Uitvoeren	• Opel Dekker Krimpen a/d IJssel, ,