


Vehicle details

VIN	VXKUPHNKS L4262604	Brand	OPEL	Maintenance date	-
Licence Plate	J9-45-BG	Model	CORSA 1.2 TURBO ELEGANCE AUTO 74KW 5d	Maintenance mileage	-
Registration date	30/06/2020	Year	2020	Exterior Color	Blue Metallic
Odometer	141 488 km	Engine size	1199	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	04/07/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 195/55/16 Summer 1.0 mm		Pirelli 195/55/16 Summer 1.0 mm	
Continental 195/55/16 Summer 1.0 mm		Continental 195/55/16 Summer 1.0 mm	

Exterior

1		Part Alloy wheel 16" Position Front left Damages Scratched Severity - Repair mode Lumpsum repair	2		Part Alloy wheel 16" Position Back left Damages Scratched Severity - Repair mode Lumpsum repair
3		Part Door Position Front left Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair	4		Part Door Position Back left Damages Dent & Chips Severity Diameter (mm) > 20 Repair mode Repair
5		Part Wing Position Back left Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair	6		Part Wing Position Back right Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair
7		Part Door Position Back right Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair	8		Part Door Position Front right Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair
9		Part Wing Position Front right Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair	10		Part Bumper Position Front Damages Scratched Severity Length (cm) > 10 Repair mode Repair

Interior damage

11		Part Fabric seat Position Front Damages Stained/dirty Severity - Repair mode Cleaning
----	---	---