



OPEL MOKKA: GLT16WZ

Vinnumber:	VXKUSHNEKNW082961	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	82527	Power Kw:	
Bodytype:	Berline	Body colour:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front		
Fueltype:	Petrol		
Engine functioning:	Yes		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Category:	Passenger Car		
Maintenance needed:	No		

Options

Number of keys total	1	Type of Tow bar	Tow bar removable
GPS storage	HD	Type of Luggage cover	Luggage space cover present
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Tyres


Summer tyres:	///			
	Fr.L.		Fr.R.	
	Re.L.		Re.R.	
Type of tires				Winter
Tyre Make Front				Other
Tyre Make Rear				Other
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0
Type of Emergency Tool	Repair kit missing
Ignition key, Missing, Replace	



Alloy rim FL, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Light repair (medium)



Bumper F, Scratch(es), Medium repair (medium)




Bumper moulding F, Scratch(es), Acceptable



Bumper spoiler F, Scratch(es), Light repair (medium)




Wing RR, Dent(s) and scratch(es), Light repair (medium)




Wheel arch (ext) R R, Scratch(es), Replace



Door RR, Scratch(es), Light repair (medium)



Door trim RR, Scratch(es), Replace



Door trim FR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Light repair (medium)



Outside rear-view mirror housing R, Scratch(es), Light repair (light)



Wing FR, Scratch(es), Light repair (light)



Wheel arch (ext) F R, Scratch(es), Replace



Tyre repair kit, Missing, Replace



Bumper R, Scratch(es), Light repair (light)



Boot cover, Broken, Replace

