



OPEL Corsa Corsa 1.2 16V

VIN NO W0L0SDL0876134854

Registration Number 0876134854



MOT Date

2025-08-01

Last Service

2021-08-06

Number of Owners

2

Last Service Mileage

115273

Number of Keys

2

First Registration Date

2007-06-16

Odometer Reading

138933 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250930084710
Inspection Date / Place	2025-09-30 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1229
Engine Size	1.2	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/muster	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	139
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Front fog lamps	Remote central locking
Stability control	Central locking	Radio	Alloys wheels
Cruise control	Remote adjusting wing mirrors	Split folding rear seats	CD Player

Leather steering wheel

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	15
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

12 Schäden




1 Schäden



48 2


Component		Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Other	Paint / Scratch / Scuff	
3	Hood	Paint / Stone Chip	
4	Fender / Front Left	Paint / Scratch / Line	
5	Rocker Panel / Center Left	Paint / Scratch / Line	
6	Door / Front Left	Paint / Scratch / Line	
7	Fender / Back Left	Paint / Scratch / Line	
8	Aeration Grid / Front Center	Interior / Broken	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Tailgate	Paint / Scratch / Line	
11	Fender / Back Right	Paint / Scratch / Line	
12	Rocker Panel / Center Right	Paint / Scratch / Line	



1. Windshield / Front
Glass Break / Impact -



2.
Paint / Scratch / Scuff -



3. Hood
Paint / Stone Chip -



4. Fender / Front Left
Paint / Scratch / Line -



5. Rocker Panel / Center Left
Paint / Scratch / Line -



6. Door / Front Left
Paint / Scratch / Line -




7. Fender / Back Left
Paint / Scratch / Line -



8. Aeration Grid / Front Center
Interior / Broken -



9. Bumper / Back
Paint / Scratch / Scuff -



10. Tailgate
Paint / Scratch / Line -



11. Fender / Back Right
Paint / Scratch / Line -



12. Rocker Panel / Center Right
Paint / Scratch / Line -



13.
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	⚠
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

AC / Heating System	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
Audio Equipment	✓	Other Equipments	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status Not Performed

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)